


OMP Flange



FORM TOOLS

Form Drill	0.000
Form Reamer	0.000
Thread Tap	0.000

CARTRIDGES

DDROMP
OSI20MP
OSI2SHOMP

DATASHEET

11-110
11-130
11-250

Where measurements are critical request certified drawings. We reserve the right to change specifications without notice.